

Please investigate and write up by \_\_\_\_\_.  
If you have any problems with this, let me know.

OHIO ENVIRONMENTAL PROTECTION AGENCY -- COMPLAINT INVESTIGATION REPORT #035

DATE RECEIVED

PERSON RECEIVING COMPLAINT

7-15-83

86 Chambers

TYPE

Telephone \_\_\_\_\_  
Visit \_\_\_\_\_  
Letter ☒ \_\_\_\_\_  
Verified \_\_\_\_\_

965673

COMPLAINANT: (Name, Address, Phone)

**non responsive**

SUSPECTED SOURCE: (Name, Address, Phone)

Grizzly Factory  
700 W. Caroline St.  
Paulding, OH 4

STATEMENT OF COMPLAINANT: (INCLUDE DIRECTIONS TO THE SITE)

An abandoned dump site with potential asbestos Pb, Cu & other industrial wastes (Grizzly → Maremont → No turn - names of companies in chronol. order)

FINDINGS:

Field investigation report attached.

RECOMMENDATIONS:

DATE OF WRITTEN FOLLOW UP 8-24-83

This site may be put on ERRIS list depending on whether asbestos material qualify. The company should be able to pay for any remediation. The NUSCO Air group will be responding to exposed asbestos problem (D. Majewski) as per NESHAP's authorization, 9-30-83.

RECTIVE ACTION AGREED TO BY SOURCE:

REMARKS:


INVESTIGATOR:

W. Badder

DATE COMPLETED:

8-24-83

FIELD NOTES ON GRIZZLY FACTORY  
PAULDING, OHIO  
8-16-83



W. Caroline

Asbestos piles were apparent, but in small quantities. Much debris around dump site but much of it finished product and asbestos containing intermediates that may or may not be readily air-borne. The dump area is free of vegetation and drains to NE and SW corners. It has a soft, spongy surface and the top 1/2 inch is grayish. It appears raised above surrounding terrain. A ditch runs along the scrubline approximately 50 feet from the fill area. Also drainage off SW corner that drains under gravel road has sediments that are very gray and perhaps contain fibrous material.

Janet W. Badden  
Hazardous Waste Scientist